

To be Filled by the Inspecting Officer (Junior Engineer)

- 1 Name of Officer : *Munera Bevi S*
- 2 Name of School : *Green Mount Public School*
- 3 Location with name of Education District/sub district : *Sankara Mangaluru Chavara ; Kollam*
- 4 Classification of building and size :
 - a. Permanent (single or double storeyed) *Building ① RCC building*
 - b. Semi-permanent *43.20 x 6.6.5 x 360*
 - c. Temporary : *43.20 x 8.6.5 x 360*
- 5 Period for which the certificate is issued *Building ② RCC bu (21.80 x 6.60) 7.85 x 6.35*
- 6 Nature of defect if any : *Building ③ A Sheet Roof (29.97 x 6.74)*
 - a. Foundations and basement
 - b. superstructure :
 - c. Doors and windows :
 - d. Work wrought and put up:
 - e. Roof :
 - f. Flooring :
 - g. Miscellaneous (cracks etc.)
- 7 Any major defects noticed which will render the building unsafe in any manner: *No*
- 8 Whether maintenance works have been done properly: *yes*
- 9 Whether the structures is sound or not for conducting classes : *Under normal weather condition*

For GREEN MOUNT PUBLIC SCHOOL

- Manager*
- 1 The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
 - 2 Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate


Certified that the school was inspected by me on *8/3/2021* 2021.....

and found to be fit/unfit to conduct classes for the period *2021-2022*.....

..... for the reasons stated above.

Place : *Chavara*

Date : *8/3/2021*



Signature
 ASSISTANT ENGINEER,
 L.S.G.D SECTION,
 CHAVARA GRAMA PANCHAYAT